

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	121713 KM
File nr. :	1445887	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NJF873 / WBA1C91050J505246 /		yr of constructionr :	/
E-File nr. :		First registration :	18/01/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	Delaware Consulting CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	
First aid kit :		Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x] MICHELIN	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x] MICHELIN	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x] MICHELIN	Tyre :	[x] OK [x] 2-4/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x] MICHELIN	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x] ANDERE	Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/FRONT DENT

[x] FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
3	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	30.00	82.80	0	0	0	0	0	0	0
105.90	15.00	82.80	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
82.80	241.80	0	324.60
HOG: 0	BG: 0		NA Deprec. 203.70
			0.00%
			TOTAL 203.70

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DARK

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/10/2017 Hour : 09:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer <hr/>	