

Date: 05/10/2017 www.vabfleetservices.be 1/4

CMI259

[ ] NOT EXECUTED [X] EFFECTIVE [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 137176 KM File nr. : Mileage start / arrival: 0 / 01438353 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EZO785 / WF0LXXGCBLDP31425 / E-File nr. : First registration: 30/04/2013 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : FORD / FOCUS **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 88g/kmDriver : Remote controls: TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: FOCUS CLIP. ECOnetic Trend 88g 105PK Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		ı	



www.vabfleetservices.be Date: 05/10/2017 2/4

Original registr. number :	OK		Service manual :		[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Varning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
vel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
ack, wheelspanner :			Filled up :	0	

### Wheels and tyres: Summer tires

		[x]	Width			Не	eight		Туре		Rim	Index	
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:		
Wheel RR:	[x]	GOODYEA	AR Tyre:		OK	[x]	2-4 /	Rim:		/	<b>Hubcap:</b> [x]	SCRATCHED	
Wheel FR:	[x]	GOODYEA	AR Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel RL:	[x]	GOODYEA	AR Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	GOODYEA	AR Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 05/10/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

#### **Bodywork \& windows**

[X] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE KUNSTSTOFDEEL

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) TE POLIJSTEN

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



Date: 05/10/2017 www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUM	STANCES		UNDER CO	UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting time: 0: Reason:	min	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	D: No	<b>I</b>		<b>I</b>				
Remark:								
Prices in EUR	without VAT							
Authorized by customer:			Executed by VAI	B Fleet Services				
Remark authorize	ed customer :							
Date :	05/10/2017	<b>Hour:</b> 12:44						
Company :								
Executed by VAB Services	Fleet							
E-Mail :	@							
Signature authorize	ed by customer							