

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	109874 KM
File nr. :	1446379	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
75KY7 / WDB2010181G082598 /		yr of constructionr :	/
E-File nr. :		First registration :	04/05/1993
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / 190	Fuel type :	PETROL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1799
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	60	R	15	V
Rear tyre	195	60	R	15	V

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR BUMPER/RIGHT/RIGHT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
285.00	110.64	110.64	115.56	0	0	0	0	0	0
285.00	110.64	110.64	115.56	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
621.84	0	0	621.84
HOG: 0	BG: 0		NA Deprec. 621.84
			0.00%
			TOTAL 621.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ELEKTRISCH BEDIENDE RUITEN [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/10/2017 Hour : 09:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	