

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	151600 KM
File nr. :	1445260	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HJD173 / WF0MXXGBWMEM73622 /		yr of constructionr :	/
E-File nr. :		First registration :	30/07/2014
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / GALAXY	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	I	Environment Class:	EURO 5
Customer company :	BALOISE BELGIUM NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/CENTER/RIGHT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR WINDOW/LEFT	OTHER DAMAGES										
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>25 LU =120.00 EUR</td> <td>0 EUR</td> <td>50 %</td> <td>120.00 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR								

[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE												
<table border="1"> <thead> <tr> <th>Number</th> <th>Code</th> <th>Description</th> <th>Unit price</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			Number	Code	Description	Unit price	Depr.	Total	0	0				
Number	Code	Description	Unit price	Depr.	Total									
0	0													

[x]	FRONT DOOR/RIGHT/REAR	DENT												
<table border="1"> <thead> <tr> <th>Number</th> <th>Code</th> <th>Description</th> <th>Unit price</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>3</td> <td>I 1 i-vab-uitd-01</td> <td>BEAT OUT DENT</td> <td>63.00 EUR</td> <td></td> <td>63.00 EUR</td> </tr> </tbody> </table>			Number	Code	Description	Unit price	Depr.	Total	3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
Number	Code	Description	Unit price	Depr.	Total									
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR									

Interior

[x]	BOOT LID IN	CARVED										
<table border="1"> <thead> <tr> <th></th> <th>Repair paint - LI</th> <th>New paint - E</th> <th>Depr.</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5 LU =24.00 EUR</td> <td>0 EUR</td> <td>50 %</td> <td>24.00 EUR</td> </tr> </tbody> </table>				Repair paint - LI	New paint - E	Depr.	Total	1	5 LU =24.00 EUR	0 EUR	50 %	24.00 EUR
	Repair paint - LI	New paint - E	Depr.	Total								
1	5 LU =24.00 EUR	0 EUR	50 %	24.00 EUR								

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	108.00 EUR	50 %	108.00 EUR
2	1	BACK WINDOW	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
177.88	420.00	63.00	0	0	0	0	0	0	0
111.88	210.00	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
108.88	552.00	0	660.88
HOG: 0	BG: 2		NA Deprec. 384.88
			0.00%
			TOTAL 384.88

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 10:08 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	