

www.vabfleetservices.be Date: 10/10/2017 1/5

CUY052

[X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 198629 KM File nr. : Mileage start / arrival: 0 / 01444915 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FMS294 / WDD2040021G154790 / E-File nr. : First registration: 21/08/2013 VFS-nr.: Color: **GREY** Make + Model : Fuel type : MERCEDES / C **DIESEL** Object nr. : Fuel: **Environment Class:** Classification: EURO 5 Customer company: Co2: BELGACOM INS/FLEET NV 109g/km Driver : Remote controls: 2 PARTIAL LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: C BER 220CDI BE Edition Avantgarde 163PK Country registration: **BELGIUM** 

Variant car:	BERLINE	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :	OK	[x]	Filled up :	0	

#### Wheels and tyres: Summer tires

		[x]	Width			н	eight	Ì		Type	Rim	Index	1 I
Wheel RES:	[x]	ANDERE	Tyre:		OK		/	Rim:			/ Hubcap:		
Wheel RR:	[x]	VREDESTEIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		
Wheel RL:	[x]	VREDESTEIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		П

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



10/10/2017 Date: www.vabfleetservices.be 3/5

DAGRIJLICHT

ST	ATUS: ACCEPTABLE	USAGE DAMA	GE			
Во	dywork \& windows					
[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAIN	Γ DAMAGE		
[x]	REAR DOOR/RIGHT/RIGHT		SCRATCH (WITHOUT	PAINT DAMAGE	E)	
[x]	REAR BUMPER/SIDE/RIGHT/FRONT		SCRATCH WITH PAIN	Γ DAMAGE		
[x]	FRONT BUMPER/LEFT/SIDE		SCRATCH WITH PAIN	Γ DAMAGE		
[x]	BONNET/CENTER/LEFT/FRONT		CHIPS			
Inte	erior					
[x]	SEAT FL		OTHER DAMAGES			
Ac	cessories and others					
[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH (WITHOUT	PAINT DAMAGE		
ST	ATUS: NOT ACCEPTA	BLE				
Во	dywork \& windows					
[x]	REAR DOOR/RIGHT/FRONT		DENT			
	Number Code	Description		Unit price	Depr.	Total
	2 I 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR
[x]	FRONT/LEFT		OTHER DAMAGES			
	Number Code	Description		Unit price	Depr.	Total
	1 I 1 i-vab-ander-01	REPAIR (PER 15')		18.74 EUR		18.74 EUR
[x]	FRONT BUMPER/RIGHT		HOLE/CRACK/TORN		DAGRIJLICHT	
		Repair paint - LI	New paint - E		Depr.	Total
	<b>4</b> 5 LU =24.00 EUR	0 EUR			50 %	24.00 EUR
Oth	ners					
	RIM REAR RIGHT					
	Number Code	Description		Unit price	Depr.	Total
	3 I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR		95.00 EUR
Pie	ces					
	Number Code	Description		Unit price	Depr.	Total

75.00 EUR

50 %

75.00 EUR



www.vabfleetservices.be Date: 10/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
18.74	63.00	95.00	99.00	0	0	0	0	0	0
18.74	63.00	95.00	49.50	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
275.74		0	99.00	176.74
226.24	NA Deprec.		BG: 0	HOG: 0
	0.00%			
226.24	TOTAL			



5/5

10/10/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Waiting time : Extra Time :  $0 \min$ 0 min Towing time :  $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date: 10/10/2017 Hour: 16:28 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer