

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	77674
File nr. :	1445903	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEP922 / WF0KXXGCBKDB72178 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / FOCUS	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	WIRELESS TECHNOLOGIES BVBA	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	FOCUS BER EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :
	[x]								[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	POLIERBAAR

STATUS: NOT ACCEPTABLE

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	0	0	0	0	0	0	0	0	0
15.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	30.00	0	30.00
HOG: 0	BG: 0		NA Deprec. 15.00
			0.00%
			TOTAL 15.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/10/2017 Hour : 16:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	