

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	174587 KM
File nr. :	1445894	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FER251 / WF0KXXGCBKDB70160 /		yr of constructionr :	/
E-File nr. :		First registration :	10/06/2013
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / FOCUS	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	WIRELESS TECHNOLOGIES BVBA	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS BER EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	ANDERE	Tyre :	[x]	NOK	/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	REAR DOOR/LEFT/CENTER	DENT		
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	INSTAP	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT		
[x]	BONNET/CENTER/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)		

Interior

[x]	DASHBORD	SCRATCHED		
[x]	STEERING WHEEL	OTHER DAMAGES		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Interior

[x]	FLOOR FL	HOLE			
		Repair paint - LI	New paint - E	Depr.	Total
	2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR

[x]	ROOF UPHOLSTERY	DIRTY				
	Number	Code	Description	Unit price	Depr.	Total
	1	I 2 speciefiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		29.16 EUR

Others

	TYRE SPARE WHEEL				
		Repair paint - LI	New paint - E	Depr.	Total
	4	5 LU =24.00 EUR		50 %	24.00 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	CARPET	150.00 EUR	50 %	150.00 EUR
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
4	1	TYRE	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	333.00	90.00	132.00	0	0	0	0	0	0
29.16	198.00	45.00	66.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
92.16	492.00	0	584.16
HOG: 0	BG: 0		NA Deprec. 338.16
			0.00%
			TOTAL 338.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/10/2017 Hour : 15:04 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	