

09/10/2017 www.vabfleetservices.be Date: 1/4

CXV6UY

[X] EFFECTIVE	[] NOT EXECUTED	[] COLLECTION	[] DELIVERY
---------------	------------------	----------------	--------------

[x] = Status Modification

HL8292 / WBAXX110200R36312 /

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	37852 KM
File nr. :	1447148	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0

yr of constructionr :

E-File nr. : First registration: 16/10/2015

VFS-nr.: Color: **BLACK** Make + Model : Fuel type : BMW / X4 **DIESEL**

Object nr. : Fuel:

Environment Class: Classification:

Customer company: Co2: **PWC** g/km

Driver : Remote controls: 2

LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 5 [x]

Vehicle type: XDRIVE 20D Country registration: LUXEMBOURG

Metallic paint: VAT over the margin - car: SUV Engine size: 1995 Variant car: Gear box : Number of places: Manueel 5 Number of gears: 6 Number of doors: 5 HP: 190 kW: 140 Fisc HP Imported vehicle: Smoked in vehicle: Animals transported: Yes Due date vehicle inspection: Extra set of tires: No Use:

Unknown

General condition:



0

www.vabfleetservices.be Date: 09/10/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: OK [x] Cert. of conformity: NOK

Cert. of reg. copy / Part 2: NOK Insurance certificate :

Warning vest : OK [x] Transport licence :

Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit : Extinguisher :

Warning triangle: OK [x]

First aid kit: OK [x] Oil level: OK [x]

Jack, wheelspanner: Filled up:

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	[x]	DUNLOP	Tyre:		OK	[x]	4-6 /	Rim:			/	Hubcap:
Wheel FR:	[x]	DUNLOP	Tyre:	[x]	OK	[x]	4-6 /	Rim:			/	Hubcap:
Wheel RR:	[x]	DUNLOP	Tyre:		OK	[x]	4-6 /	Rim:			/	Hubcap:
Wheel RFS	[v]		Tyre ·		OK		/	Dim ·			/	Hubean •

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 09/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

	dywork \& windows	USAGE DAMA	NGE		
x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
x]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	BORD PORTE	
κ]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	IN	
]	FRONT DOOR/LEFT/CENTER		DENT		
[]	FRONT DOOR/RIGHT/REAR		DENT		
ST	ATUS: NOT ACCEPTA	BLE			
Во	dywork \& windows				
:]	REAR BUMPER/RIGHT/CORNER		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	0 EUR		50 %	·
		Repair paint - LI	New paint - E	Depr.	Total
	2 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR
]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
	1 I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
ie	ces				
	Number Code	Description	Unit price	Depr.	Total

L							
•		Number	Code	Description	Unit price	Depr.	Total
	2	1	GARNITURE SPOILER INF		250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	298.00	0	0	0	0	0	0	0	0
115.56	149.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
115.56	298.00	0		413.56
HOG: 0	BG: 2		NA Deprec.	264.56
			0.00%	
			TOTAL	264.56



www.vabfleetservices.be Date: 09/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMST	ANCES		UNDER CO	ONDITION - DUSTY VEHICLE	
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min
NOT EXECUTED : Reason :	No			I	
Remark :	ODEUR DE CI	GARETTE INT [x]			
Prices in EUR wi	thout VAT				
Authorized by customer :			Executed by VAI	B Fleet Services	
Remark authorized cu	istomer :				
Date :	09/10/2017	Hour: 12:56			
Company: Executed by VAB Flee Services	et				
E-Mail :	@				
Signature authorized by	/ customer				