

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	108520 KM
File nr. :	1445682	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRK526 / WF0JXXGAJJCE39506 /		yr of constructionr :	2012 / 00
E-File nr. :		First registration :	31/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	FORD / FIESTA	Fuel type :	DIESEL
Object nr. :	700660	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TRANSPORT VAN LOON	Co2:	87g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	FIESTA BER Trend ECONetic 87g.95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :		
First aid kit :		Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	175	65	R	14	H
Rear tyre	175	65	R	14	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF/CENTER/RIGHT	DENT	3X
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
[x]	BONNET/CENTER/LEFT	DENT	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR
[x]	ROOF STYLE/FRONT/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	176.14 EUR		50 %	176.14 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

1	2	3	4	5	6	7	8	9	10
169.44	169.44	176.14	0	0	0	0	0	0	0
84.72	84.72	88.07	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	515.02	0	515.02
HOG: 0	BG: 1		NA Deprec. 257.51
			0.00%
			TOTAL 257.51

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 10:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	