

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	38318 KM
File nr. :	1445619	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KPY659 / WDD1760121V074770 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	45730	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	KPMG TAX AND LEGAL ADVISERS	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		[x]
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :			
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
2	15 LU =72.00 EUR	0 EUR	235.80 EUR	50 %	307.80 EUR	
[x]	REAR LIGHT/RIGHT/CORNER		HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

Others

	HUB CAP REAR RIGHT					
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR			50 %		
	HUB CAP FR					
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR			50 %		

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
60.00	651.00	114.00	211.80	0	0	0	0	0	0
30.00	325.50	57.00	105.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1036.80	0	1036.80
HOG: 0	BG: 0		NA Deprec. 518.40
			0.00%
			TOTAL 518.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 10:08 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	