

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	96019 KM
<b>File nr. :</b>	1444917	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FER153 / WF0KXXGCBKDB70288 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	10/06/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	FORD / FOCUS	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	WIRELESS TECHNOLOGIES BVBA	<b>Co2:</b>	88g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	FOCUS BER EConetic Trend 88g 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	OK
Warning vest :	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	2-4/	Rim :		Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	2-4/	Rim :		Hubcap :	[x] SCRATCHED
Wheel FR :	[x]	MICHELIN	Tyre :	OK	2-4/	Rim :		Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	2-4/	Rim :		Hubcap :	[x] SCRATCHED
Wheel RES:	[x]	MICHELIN	Tyre :	OK	>6/	Rim :		Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	WINTER H
Rear tyre	205	55	R	16	WINTER H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/CENTER/RIGHT	DENT	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	INTERIEUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/FRONT	DENT	
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	INTERIEUR
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS	

**Interior**

[x] DOOR IN REAR L SCRATCHED

**STATUS: NOT ACCEPTABLE**

**Bodywork \& windows**

[x] REAR DOOR/LEFT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR DOOR/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] WINDSCREEN/LEFT WINDOW DAMAGE ZWARTE BAND

	Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR

**Interior**

[x] SEAT FL STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

[x] SEAT REAR L STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

[x] BACK SHELF MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR	50 %	

[x] BOOT LID IN MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR	50 %	

**Accessories and others**

VEH COVERED WITH STICKERS STICKER(S)

Number	Code	Description	Unit price	Depr.	Total
0	0				

<b>Pieces</b>
---------------

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK SHELF	50.00 EUR	50 %	50.00 EUR
<hr/>					
Number	Code	Description	Unit price	Depr.	Total
1	1	SET KNOP	5.00 EUR	50 %	5.00 EUR
<hr/>					
Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
84.16	487.20	63.00	63.00	0	0	0	0	0	0
56.66	243.60	63.00	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
155.16	542.20	0	<b>697.36</b>
HOG: 0	BG: 0		NA Deprec. 426.26
			0.00%
			<b>TOTAL 426.26</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 11/10/2017 <b>Hour :</b> 11:01 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	