

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 144861 KM |
| File nr. : | 1444173 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DKO637 / WDF63960113720764 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 11/06/2012 |
| VFS-nr. : | | Color : | RED |
| Make + Model : | MERCEDES / VITO | Fuel type : | DIESEL |
| Object nr. : | 12314 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | MIELE NV 421000/800 | Co2: | 206g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | TRUCK, LORRY | Seats (minivan) : | 0 |
| Vehicle type : | VITO 110 B/F SWB 95PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | |
| Variant car: | BESTELWAGEN | Engine size: | 2143 |
| Gear box : | Manueel | Number of places: | 3 |
| Number of gears: | 6 | Number of doors: | 4 |
| HP: | 95 | kW: | 70 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|---------------------------------|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : | |
| Wheel RL : | [x] | SEMPERIT | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : | |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel RR : | [x] | SEMPERIT | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : [x] MISSING/INCOMPLETE | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 195 | 65 | R | 16 | |
| Rear tyre | 195 | 65 | R | 16 | |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|-------------------------|--------------------------------|----------|--|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE | | |
| [x] | REAR DOOR/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) | POLIEREN | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | |
|-----|----------------------------|---------------------------|----------------------|--------------|
| [x] | REAR LIGHT/LEFT/CORNER | HOLE/CRACK/TORN | | |
| | | Repair paint - LI | New paint - E | Depr. |
| 5 | 0 LU =0.00 EUR | 0 EUR | | 50 % |
| | | Repair paint - LI | New paint - E | Depr. |
| 5 | 5 LU =24.00 EUR | 0 EUR | | 50 % |
| | | | | 24.00 EUR |
| [x] | REAR MUDGUARD/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | +DEUKEN | |
| | | Repair paint - LI | New paint - E | Depr. |
| 2 | 0 LU =0.00 EUR | 231.15 EUR | | 50 % |
| | | | | 231.15 EUR |
| [x] | FRONT DOOR/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. |
| 3 | 0 LU =0.00 EUR | 238.76 EUR | | 50 % |
| | | | | 238.76 EUR |

Interior

| | | | | | | |
|-----|---------------|----------------------------------|--------------------|-------------------|--------------|--------------|
| [x] | SEAT FR | DIRTY | | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 4 | I 2 | bestelwagen-cabine-a-vab-rein-05 | CLEANING INTERIOR | 11.47 EUR | | 22.94 EUR |

Others

HUB CAP REAR RIGHT

| | | | | | |
|---|----------------|--------------------------|----------------------|--------------|--------------|
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | | | 50 % | |

Pieces

| | | | | | | |
|---|---------------|-------------|--------------------|-------------------|--------------|--------------|
| | Number | Code | Description | Unit price | Depr. | Total |
| 1 | 1 | | WHEEL CAP | 22.50 EUR | 50 % | 22.50 EUR |
| | Number | Code | Description | Unit price | Depr. | Total |
| 5 | 1 | | REAR LIGHT | 67.50 EUR | 50 % | 67.50 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|-------|-------|---|---|---|---|----|
| 22.50 | 231.15 | 238.76 | 22.94 | 91.50 | 0 | 0 | 0 | 0 | 0 |
| 11.25 | 115.58 | 119.38 | 22.94 | 45.75 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 22.94 | 583.91 | 0 | 606.85 |
| HOG: 0 | BG: 3 | | NA Deprec. 314.90 |
| | | | 0.00% |
| | | | TOTAL 314.90 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 06/10/2017 Hour : 10:20 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |