

Date: www.vabfleetservices.be 27/09/2017 1/4

**CQNAWY** 

#### [ ] NOT EXECUTED [X] EFFECTIVE [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 114376 KM File nr. : Mileage start / arrival: 0 / 01441533 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FLU170 / WF0GXXGBBGDP14309 / E-File nr. : First registration: 09/08/2013 VFS-nr.: Color: **BROWN** Make + Model : Fuel type : FORD / MONDEO **DIESEL** Object nr. : Fuel: **Environment Class:** Classification: EURO 5 Customer company: Co2: ON SEMICONDUCTOR BELGIUM 112g/km **BVBA** Driver: Remote controls: 2 Covering: LEATHER Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0[x]Vehicle type: MONDEO CLIP Econetic Titanium 115PK Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1560			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	116	kW:	85			
Fisc HP		Imported vehicle:	No			
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



27/09/2017 Date: www.vabfleetservices.be 2/4

Original registr. number: OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity:	OK	
Cert. of reg. copy / Part 2: OK	[x]	Insurance certificate :		
Warning vest: OK	[x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit: OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :		Filled up :	0	

## Wheels and tyres: Summer tires

Whee	el RES:	[x]	[x]	Tyre : Width		OK	н	eight	Rim :	Type	/ I	Hubcap :	Index
	el RR :	[x]	MICHELIN	•		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Whee	el FR :	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Whee	el RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Whee	el FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 27/09/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

#### **Bodywork \& windows**

[X] REAR DOOR/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 27/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES	NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED :	: No	<b>I</b>		<u> </u>				
Remark :								
Prices in EUR v	vithout VAT							
Authorized by customer:			Executed by VAB Fleet S	Services				
Remark authorized	customer :							
Date :	27/09/2017	<b>Hour:</b> 13:05						
Company :								
Executed by VAB F Services	leet							
E-Mail :	@							
Signature authorized	by customer							