

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	107780 KM
<b>File nr. :</b>	1444895	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FMS221 / WDD2040021A897111 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	21/08/2013
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	MERCEDES / C	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INS/FLEET NV	<b>Co2:</b>	109g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	PARTIAL LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	C BER 220CDI BE Edition Avantgarde 163PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BERLINE	<b>Engine size:</b>	2143
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	4
<b>HP:</b>	163	<b>kW:</b>	120
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	OK
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :		/	Hubcap :
Wheel RL :	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x]	VREDESTEIN	Tyre :	OK	4-6/	Rim :	[x]		/ Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	>6/	Rim :			/ Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/CENTER/RIGHT DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	WIND SCREEN/BELOW/RIGHT	WINDOW DAMAGE	ZWARTE RAND		
	Repair paint - LI	New paint - E	Depr.	Total	
1	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
487.20	0	0	0	0	0	0	0	0	0
243.60	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	487.20	0	<b>487.20</b>
HOG: 0	BG: 0		NA Deprec. 243.60
			0.00%
			<b>TOTAL 243.60</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 10/10/2017 <b>Hour :</b> 13:56 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b>	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	