

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	206108 KM
<b>File nr. :</b>	1444312	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GXL752 / WVWZZZ7NZEV040234 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	27/05/2014
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLKSWAGEN / SHARAN	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>	I	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	AIR LIQUIDE BELGE SA (PO 4505810958)	<b>Co2:</b>	143g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1968
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Winter tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	KLÉBER	Tyre :	OK		/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	M+S
Rear tyre	205	60	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	ROOF STYLE/FRONT/RIGHT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

### Interior

[x]	BOOT LID IN	CARVED
-----	-------------	--------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR

### Interior

[x]	LUGGAGE COVER	MISSING/INCOMPLETE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	0 EUR		50 %	

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		14.58 EUR

HUB CAP REAR RIGHT

		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
4	1	LUGGAGE COVER	288.00 EUR	50 %	288.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	382.02	264.21	288.00	72.00	0	0	0	0	0
14.58	191.01	132.10	144.00	36.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	1006.23	0	<b>1020.81</b>
HOG: 0	BG: 2		NA Deprec. 517.70
			0.00%
			<b>TOTAL 517.70</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 05/10/2017 <b>Hour :</b> 14:08 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	