

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	54586 KM
<b>File nr. :</b>	1448043	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FTB702 / WAUZZZ8X4EB043378 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	16/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	AUDI / A1	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	16491	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	INTER IKEA HOLDING SERVICES SA	<b>Co2:</b>	110g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	A1 BER Ambition S-tr.90PK Aut.	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	4
<b>Number of gears:</b>		<b>Number of doors:</b>	3
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	Yes	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x] MICHELIN	Tyre :	OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x] MICHELIN	Tyre :	OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel FR :	[x] MICHELIN	Tyre :	[x] OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RR :	[x] MICHELIN	Tyre :	OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RES:	[x]	Tyre :	OK /	Rim :		/ Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	16	V
Rear tyre	215	45	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :		/ Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT

### Interior

[x]	FLOOR BOOT	OTHER DAMAGES
-----	------------	---------------

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	-------------------------------	--------------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	10 LU =48.00 EUR		169.44 EUR		50 %	217.44 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	25 LU =120.00 EUR		246.56 EUR		50 %	366.56 EUR
[x]	FRONT DOOR/RIGHT/FRONT	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	25 LU =120.00 EUR		254.68 EUR		50 %	374.68 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		176.14 EUR		50 %	176.14 EUR
[x]	BONNET/CENTER/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR		232.06 EUR		50 %	232.06 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I1 i-vab-geur-01	ODOUR TREATMENT	152.58 EUR		152.58 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
152.58	232.06	217.44	366.56	550.82	285.00	0	0	0	0
152.58	116.03	108.72	183.28	275.41	285.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
437.58	1366.88	0	<b>1804.46</b>
HOG: 0	BG: 1		NA Deprec. 1121.02
			0.00%
			<b>TOTAL 1121.02</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/10/2017 <b>Hour :</b> 12:54 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	