

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

|                                     |                               |                                 |                               |
|-------------------------------------|-------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING               | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                               | <b>Mileage :</b>                | 150719 KM                     |
| <b>File nr. :</b>                   | 1448188                       | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> | 1HUU476 / WAUZZZ8K7FA044049 / | <b>Mileag ref. service :</b>    | 0                             |
| <b>E-File nr. :</b>                 |                               | <b>yr of constructionr :</b>    | /                             |
| <b>VFS-nr. :</b>                    |                               | <b>First registration :</b>     | 08/10/2014                    |
| <b>Make + Model :</b>               | AUDI / A4 AVANT               | <b>Color :</b>                  | GREY                          |
| <b>Object nr. :</b>                 | 66704                         | <b>Fuel type :</b>              | DIESEL                        |
| <b>Classification :</b>             | F                             | <b>Fuel :</b>                   |                               |
| <b>Customer company :</b>           | HOBERG NV                     | <b>Environment Class:</b>       | EURO 5                        |
| <b>Driver :</b>                     |                               | <b>Co2:</b>                     | 129g/km                       |
| <b>Covering :</b>                   | TISSUE                        | <b>Remote controls:</b>         | 2                             |
| <b>Vehicle kind :</b>               | VEHICLE                       | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle type :</b>               |                               | <b>Seats (minivan) :</b>        | 0                             |
|                                     |                               | <b>Country registration :</b>   | BELGIUM                       |

|                                     |                   |                            |         |
|-------------------------------------|-------------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   |                   | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BREAK             | <b>Engine size:</b>        | 1968    |
| <b>Gear box :</b>                   | Automaat algemeen | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 0                 | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 136               | <b>kW:</b>                 | 100     |
| <b>Fisc HP</b>                      |                   | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         |                   | <b>Smoked in vehicle:</b>  |         |
| <b>Due date vehicle inspection:</b> |                   | <b>Extra set of tires:</b> | No      |
|                                     |                   | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |                   |                            |         |

|                              |    |                         |                       |     |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number :   | OK | Service manual :        | OK                    | [x] |
| Cert. of reg. / Part 1:      | OK | [x]                     | Cert. of conformity : | OK  |
| Cert. of reg. copy / Part 2: |    | Insurance certificate : |                       |     |
| Warning vest :               | OK | [x]                     | Transport licence :   |     |
| Tax certificate :            |    | Navigation CD/SD/DVD    | OK                    | [x] |
| Fuel card :                  |    | Car radio :             | OK                    | [x] |
| Mobile phone kit :           |    | Extinguisher :          | OK                    | [x] |
| First aid kit :              | OK | [x]                     | Warning triangle :    | OK  |
| Jack, wheelspanner :         | OK | [x]                     | Oil level :           | OK  |
|                              |    | Filled up :             | 0                     |     |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |      |       |       |                 |
|------------|-----|----------|--------|-----|-----|------|-------|-------|-----------------|
| Wheel FL:  | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | /     | Hubcap :        |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | /     | Hubcap :        |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK  | [x]  | 2-4/  | Rim : | /               |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/ | Rim : | [x]   | WHEEL SCRATCHED |
| Wheel RES: | [x] |          | Tyre : | OK  | /   |      | Rim : | /     | Hubcap :        |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 55     | R    | 16  | V     |
| Rear tyre  | 225   | 55     | R    | 16  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :



## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

### Interior

[x] DOOR IN REAR L SCRATCHED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT DENT

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 3 0 LU =0.00 EUR | 211.80 EUR        |               | 50 %  | 211.80 EUR |

[x] FRONT THRESHOLD/LEFT/FRONT DENT

|                    | Repair paint - LI | New paint - E | Depr. | Total      |
|--------------------|-------------------|---------------|-------|------------|
| 2 15 LU =72.00 EUR | 310.50 EUR        |               | 50 %  | 382.50 EUR |

[x] FRONT MUDGUARD/LEFT/CENTER DENT

| Number | Code              | Description   | Unit price | Depr. | Total     |
|--------|-------------------|---------------|------------|-------|-----------|
| 4      | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR  |       | 63.00 EUR |

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 211.80 EUR        |               | 50 %  | 211.80 EUR |

### Others

RIM REAR RIGHT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 5      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

| 1      | 2      | 3      | 4     | 5     | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|-------|-------|---|---|---|---|----|
| 211.80 | 382.50 | 211.80 | 63.00 | 95.00 | 0 | 0 | 0 | 0 | 0  |
| 105.90 | 191.25 | 105.90 | 63.00 | 95.00 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 158.00     | 806.10      | 0       | 964.10            |
| HOG: 0     | BG: 0       |         | NA Deprec. 561.05 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 561.05      |



[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 16/10/2017 <b>Hour :</b> 09:28<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |