

CZ1ZX2

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                        |                                 |                               |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING        | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                        | <b>Mileage :</b>                | 96258 KM                      |
| <b>File nr. :</b>                   | 1448064                | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                        | <b>Mileag ref. service :</b>    | 0                             |
| 1FSA096 / WAUZZZ8V1EA069229 /       |                        | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                        | <b>First registration :</b>     | 07/10/2013                    |
| <b>VFS-nr. :</b>                    |                        | <b>Color :</b>                  | BLUE                          |
| <b>Make + Model :</b>               | AUDI / A3              | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 |                        | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                        | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | B&M CONSULTING BVBA    | <b>Co2:</b>                     | 99g/km                        |
| <b>Driver :</b>                     |                        | <b>Remote controls:</b>         | 1                             |
| <b>Covering :</b>                   | TISSUE                 | <b>Number keys :</b>            | 1 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | A3 SB Attraction 105PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No      | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 |         | <b>Engine size:</b>        | 1598    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 6       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 105     | <b>kW:</b>                 | 77      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> | No      |
|                                     |         | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |         |                            |         |

|                              |        |                         |        |
|------------------------------|--------|-------------------------|--------|
| Original registr. number :   | OK     | Service manual :        | OK     |
| Cert. of reg. / Part 1:      | OK [x] | Cert. of conformity :   | OK     |
| Cert. of reg. copy / Part 2: | [x]    | Insurance certificate : |        |
| Warning vest :               | OK [x] | Transport licence :     |        |
| Tax certificate :            |        | Navigation CD/SD/DVD    | [x]    |
| Fuel card :                  |        | Car radio :             | OK     |
| Mobile phone kit :           |        | Extinguisher :          | OK     |
| First aid kit :              | OK [x] | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         |        | Oil level :             | OK [x] |
|                              |        | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |        |        |       |                 |            |
|------------|-----|----------|--------|-----|-----|--------|--------|-------|-----------------|------------|
| Wheel FL:  | [x] | MICHELIN | Tyre : | OK  | [x] | 1.6-2/ | Rim :  |       | /               | Hubcap :   |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/   | Rim :  | [x]   | WHEEL SCRATCHED | / Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK  | [x]    | 1.6-2/ | Rim : |                 | / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK  | [x] | 2-4/   | Rim :  | [x]   | WHEEL SCRATCHED | / Hubcap : |
| Wheel RES: | [x] | MICHELIN | Tyre : | OK  |     | >6/    | Rim :  |       |                 | / Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 16  | H     |
| Rear tyre  | 205   | 55     | R    | 16  | H     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                          |                                |
|-----|--------------------------|--------------------------------|
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE      |
| [x] | REAR DOOR/LEFT/CENTER    | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT DOOR/RIGHT/REAR    | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | BONNET/CENTER/LEFT/FRONT | CHIPS                          |
| [x] | FRONT BUMPER/RIGHT       | CHIPS                          |

### Accessories and others

|                               |                                |
|-------------------------------|--------------------------------|
| OUTSIDE MIRROR RIGHTHAND SIDE | SCRATCH (WITHOUT PAINT DAMAGE) |
|-------------------------------|--------------------------------|

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                           |                          |                      |              |              |
|-----|--------------------------|---------------------------|--------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |                          |                      |              |              |
|     |                          |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 1   | 0 LU =0.00 EUR           |                           | 169.44 EUR               |                      | 50 %         | 169.44 EUR   |

### Interior

|     |                 |        |                          |                      |              |              |
|-----|-----------------|--------|--------------------------|----------------------|--------------|--------------|
| [x] | BOOT LID IN     | CARVED |                          |                      |              |              |
|     |                 |        | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 5 LU =24.00 EUR |        | 0 EUR                    |                      |              | 24.00 EUR    |

### Pieces

| Number | Code | Description     | Unit price | Depr. | Total     |
|--------|------|-----------------|------------|-------|-----------|
| 2      | 1    | UPHOLSTERY DOOR | 72.00 EUR  |       | 72.00 EUR |

| 1      | 2     | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|---|---|---|---|---|---|---|----|
| 169.44 | 96.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 84.72  | 96.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 0          | 265.44      | 0       | <b>265.44</b>       |
| HOG: 0     | BG: 1       |         | NA Deprec. 180.72   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 180.72</b> |



[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 13/10/2017 <b>Hour :</b> 12:20<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| <b>Signature authorized by customer</b><br><br>  |                                |