

www.vabfleetservices.be Date: 17/10/2017 1/4

CZCK72

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	203569 KM
File nr. :	1448288	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EJR652 / WAUZZZ8K5DN0	34772 /	yr of constructionr :	/
E-File nr. :		First registration :	01/01/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	48582	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	SPIE BELGIUM NV/SA	Co2:	115g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 BER TDie 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BERLINE	Engine size:	1968				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	4				
нр:	163	kW:	120				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRII	OGESTONE	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	BRII	OGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RES:	[x]	AND	ERE	Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]	W	idth			Н	eight			Туре		Rim	Index
From	ıt tyre		2	225				55			R		16	V

ı	Front tyre	225	55	R	16	V
	Rear tyre	225	55	R	16	V
ı						

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap :
1					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[X] REAR DOOR/RIGHT/CORNER/BELOW SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/RIGHT/CENTER DENT

[x] WINDSCREEN/CENTER/RIGHT CHIPS

[x] BONNET/CENTER/LEFT/FRONT CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 17/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		NORMAL CONCLUSION							
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min					
NOT EXECUTED : Reason :	No			<u> </u>						
Remark:										
Prices in EUR v	vithout VAT									
Authorized by customer:			Executed by VAB Fleet S	Services						
Remark authorized	customer :									
Date :	17/10/2017	Hour: 15:26								
Company :										
Executed by VAB F. Services	leet									
E-Mail :	@									
Signature authorized	by customer									