

www.vabfleetservices.be Date: 13/10/2017 1/4

CYMQ2C

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	131222 KM
File nr. :	1447735	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPJ808 / WAUZZZ8K1EN01	0485 /	yr of constructionr :	/
E-File nr. :		First registration :	13/09/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	67525	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	EPA NV	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 BER TDie 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
нр:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		<u> </u>	



Date: 13/10/2017 www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

1 –					205				60			D.		1.6	T.7
	Fron	t tyre			205			(60			R		16	V
			[x]		Width			Не	eight			Type		Rim	Index
Who	eei KES:	[x]	AND	EKE	Tyre :		UK		/	Rim :			,	Hubcap:	
1371.	eel RES:	fw1	AND	EDE	Trong		OK		,	Dim.				. Hubaan .	
Who	eel RR :	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:			,	Hubcap:	
Who	eel FR :	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	4-6 /	Rim:			,	Hubcap:	
Who	eel RL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:			,	Hubcap:	
Who	eel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	

[A]	vviatii	Height	Type	Tuni	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V
•					

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/LEFT/FRONT DENT

[x] FRONT BUMPER/CENTER/LEFT DENT

STATUS: NOT ACCEPTABLE

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
14.58	0	0	0	0	0	0	0	0	0
14.58	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
14.58	0	0		14.58
HOG: 0	BG: 0		NA Deprec.	14.58
			0.00%	

TOTAL

14.58



www.vabfleetservices.be Date: 13/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS'	TANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No							
Remark:								
Prices in EUR w	vithout VAT							
Authorized by customer :			Executed by VAB Fleet S	Services				
Remark authorized	customer :							
Date : Company :	13/10/2017	Hour: 07:57						
Executed by VAB Fl Services	leet							
E-Mail :	@							
Signature authorized	by customer							