

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	166075 KM
File nr. :	1446583	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CXG828 / WAUZZZ8R9CA093925 /		yr of constructionr :	/
E-File nr. :		First registration :	19/03/2012
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :	35845	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	NORTHGATEARINSO BV	Co2:	184g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q5 S Tronic DPF 163PK aut	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	SUV	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest : NOK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	55	R	19	V
Rear tyre	235	55	R	19	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF/REAR/RIGHT	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/FRONT/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/LEFT	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
-----	-------------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
-----	---------------------------	------

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
0	254.16	63.00	0	0	0	0	0	0	0
0	127.08	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	254.16	0	317.16
HOG: 0	BG: 2		NA Deprec. 190.08
			0.00%
			TOTAL 190.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 15:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	