

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	16046 KM
File nr. :	1444818	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NAE742 / WBA2E510X05C92636 /		yr of constructionr :	2016 / 00
E-File nr. :		First registration :	04/01/2016
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 2 GRAN TOURER	Fuel type :	DIESEL
Object nr. :	32600	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	UZ ANTWERPEN VZW	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	17	W
Rear tyre	205	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER DENT
- [x] REAR DOOR/LEFT/FRONT DENT
- [x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] WINDSCREEN/CENTER/LEFT CHIPS

STATUS: NOT ACCEPTABLE

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	0	0	0	0	0	0	0	0	0
95.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	0	0	95.00
HOG: 0	BG: 1		NA Deprec. 95.00
			0.00%
			TOTAL 95.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 11:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	