

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	89526 KM
<b>File nr. :</b>	1448028	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DLK007 / WBAUY51090F226859 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	15/06/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / 3	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	3779	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	MEDIAHUIS NV	<b>Co2:</b>	119g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	3 TOURING 316d 116PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	116	<b>kW:</b>	85
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x] MICHELIN	Tyre :	OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x] MICHELIN	Tyre :	OK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel FR :	[x] MICHELIN	Tyre :	[x] NOK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RR :	[x] MICHELIN	Tyre :	[x] NOK [x] 4-6/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RES:	[x]	Tyre :	OK /	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	EN DEUK
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	EN DEUK
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	POL
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	ONDER
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	ONDER

### Interior

[x]	SEAT FL	OTHER DAMAGES
-----	---------	---------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
2	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR	
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	11	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Others

	TYRE REAR RIGHT				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	5 LU =24.00 EUR			50 %	24.00 EUR

TYRE FRONT RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR		50 %	24.00 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
5	1	TYRE	108.00 EUR	50 %	108.00 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	TYRE	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	481.50	63.00	95.00	264.00	0	0	0	0	0
105.90	240.75	63.00	95.00	132.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	957.30	0	<b>1115.30</b>
HOG: 0	BG: 0		NA Deprec. 636.65
			0.00%
			<b>TOTAL 636.65</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/10/2017 <b>Hour :</b> 15:26 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	