

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	171738 KM
<b>File nr. :</b>	1448105	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EVW937 / WBA1N31020J710739 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	03/04/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	BMW / 1	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	KBC BANK NV	<b>Co2:</b>	99g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	1 SPORTSHATCH 116d Eff.Dyn.Ed.116PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	4
<b>Number of gears:</b>	6	<b>Number of doors:</b>	3
<b>HP:</b>	116	<b>kW:</b>	85
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate : OK [x]
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 0-1.6/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 0-1.6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 0-1.6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 0-1.6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR THRESHOLD/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/LEFT/CENTER DENT +KRAS

	Repair paint - LI	New paint - E	Depr.	Total
4 20 LU =96.00 EUR	308.20 EUR		50 %	404.20 EUR

[x] REAR WINDOW STYLE/LEFT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR MUDGUARD/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
7 10 LU =48.00 EUR	308.20 EUR		50 %	356.20 EUR

[x] FRONT DOOR/LEFT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR

[x] FRONT DOOR/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT MUDGUARD/LEFT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 10 LU =48.00 EUR	220.18 EUR		50 %	268.18 EUR

[x] BONNET/CENTER/RIGHT DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

[x] FRONT MUDGUARD/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
8 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

### Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1 DOOR FL		502.80 EUR	50 %	502.80 EUR
6	1 STRIP		100.00 EUR	50 %	100.00 EUR
8	1 MIRROR		120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
290.08	268.18	1082.52	404.20	63.00	311.80	356.20	168.00	63.00	158.00
145.04	134.09	541.26	202.10	63.00	155.90	178.10	84.00	63.00	158.00

INNOVATIVE	TRADITIONAL	GENERAL	
284.00	2880.98	0	<b>3164.98</b>
HOG: 0	BG: 0		NA Deprec. 1724.49
			0.00%
			<b>TOTAL 1724.49</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/10/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	