

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	84367 KM
File nr. :	1447248	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HRY687 / WBA1C91080P695783 /		yr of constructionr :	/
E-File nr. :		First registration :	17/09/2014
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 1 HATCH	Fuel type :	DIESEL
Object nr. :	32539	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG ACCOUNTANTS CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] BROKEN / CRACKED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER DENT

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/CENTER DENT

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
2	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

Interior

[x] BOOT LID IN CARVED

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
110.64	82.80	36.00	0	0	0	0	0	0	0
110.64	82.80	18.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
193.44	36.00	0	229.44
HOG: 0	BG: 2		NA Deprec. 211.44
			0.00%
			TOTAL 211.44

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 10:19 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	