

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	146732 KM
File nr. :	1449383	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWG598 / VF7AAFHZ0C8282204 /		yr of constructionr :	2012 / 00
E-File nr. :		First registration :	17/09/2012
VFS-nr. :		Color :	WHITE
Make + Model :	CITROEN / NEMO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	P	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1248
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	[x]	Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	H
Rear tyre	185	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	OTHER DAMAGES	VERVORMD		
		Repair paint - LI	New paint - E		
		Depr.	Total		
2	15 LU =72.00 EUR	0 EUR	50 %	72.00 EUR	
[x]	REAR DOOR/CENTER/LEFT	DENT	DEUR L		
	Number Code	Description	Unit price	Depr.	Total
3	11 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	DEUR R + ROEST		
		Repair paint - LI	New paint - E		
		Depr.	Total		
4	0 LU =0.00 EUR	226.26 EUR	50 %	226.26 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	VERVORMD		
		Repair paint - LI	New paint - E		
		Depr.	Total		
1	20 LU =96.00 EUR	231.15 EUR	50 %	327.15 EUR	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR

1	2	3	4	5	6	7	8	9	10
327.15	329.40	63.00	226.26	0	0	0	0	0	0
163.58	164.70	63.00	113.13	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	882.81	0	945.81
HOG: 0	BG: 3		NA Deprec. 504.40
			0.00%
			TOTAL 504.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 10:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	