

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	97881 KM
File nr. :	1446909	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FHO849 / VF7YCTMFC12374907 /		yr of constructionr :	/
E-File nr. :		First registration :	01/07/2013
VFS-nr. :		Color :	WHITE
Make + Model :	CITROEN / JUMPER	Fuel type :	DIESEL
Object nr. :	57868	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	COMPTOIR ELECTRIQUE DE CHENEE SA	Co2:	229g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	JUMPER 35 B/F LWB L3H2 Fresh(EU5)130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	S
Rear tyre	215	70	R	15	S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	WINDOW STYLE FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/FRONT/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/FRONT/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

Interior

[x]	FLOOR BOOT	SCRATCHED
[x]	BOOT IN L	OTHER DAMAGES
[x]	BOOT IN R	OTHER DAMAGES

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR
[x]	REAR WINDOW STYLE/RIGHT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	40 LU =192.00 EUR	231.15 EUR		50 %	423.15 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	40 LU =192.00 EUR	232.88 EUR		50 %	424.88 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
4 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
329.40	423.15	424.88	138.00	0	0	0	0	0	0
164.70	211.58	212.44	69.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1315.43	0	1315.43
HOG: 0	BG: 3		NA Deprec. 657.72
			0.00%
			TOTAL 657.72

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : CONTROLE DAKPANEEL OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 15:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	