

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	10784 KM
File nr. :	1449230	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PJN141 / ZFA25000002B18000 /		yr of constructionr :	/
E-File nr. :		First registration :	14/07/2016
VFS-nr. :		Color :	WHITE
Make + Model :	FIAT / DUCATO	Fuel type :	
Object nr. :	ONBEKEND	Fuel :	
Classification :	DELIVERY VAN C	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	PARTIAL LEATHER	Number keys :	4 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2297
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :		Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	V
Rear tyre	215	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] WINDOW REAR DOOR/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
2 15 LU =72.00 EUR	0 EUR	176.85 EUR	50 %	248.85 EUR

[x] REAR LIGHT/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Interior

[x] FLOOR BOOT OTHER DAMAGES

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	STEUN	50.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	REAR LIGHT	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
74.00	506.25	54.00	0	0	0	0	0	0	0
37.00	253.12	27.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	634.25	0	634.25
HOG: 0	BG: 3		NA Deprec. 317.12
			0.00%
			TOTAL 317.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 16:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	