

CVO4P7

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	98189 KM
File nr. :	1445483	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GMZ846 / VF7NC9HP0EY514380 /		yr of constructionr :	/
E-File nr. :		First registration :	12/02/2015
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / C4	Fuel type :	DIESEL
Object nr. :	42512	Fuel :	
Classification :	B	Environment Class:	EURO 5
Customer company :	IMEC VZW	Co2:	104g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT	MEERDERE OP KARAKTERLIJN		
		Repair paint - LI	New paint - E	Depr.	Total
4	15 LU =72.00 EUR	308.20 EUR		50 %	380.20 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	15 LU =72.00 EUR	308.20 EUR		50 %	380.20 EUR
[x]	ROOF/REAR/RIGHT	OTHER DAMAGES	CHEMISCHE		
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
6	5 LU =24.00 EUR	318.35 EUR		50 %	342.35 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	11.47 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
11.47	211.80	318.35	380.20	380.20	562.53	190.00	481.50	0	0
11.47	105.90	159.18	190.10	190.10	281.26	190.00	240.75	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
201.47	2334.58	0	2536.05
HOG: 0	BG: 0		NA Deprec. 1368.76
			0.00%
			TOTAL 1368.76

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 10:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	