

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	97587 KM
File nr. :	1449039	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FOR163 / WBAVY11010VW90554 /		yr of constructionr :	/
E-File nr. :		First registration :	09/09/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / X1	Fuel type :	DIESEL
Object nr. :	40285	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	THESE DAYS NV	Co2:	128g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/LEFT	DENT
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE						
			Repair paint - LI	New paint - E	Depr.	Total		
2	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR		
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE						
			Number	Code	Description	Unit price	Depr.	Total
3	1	i-vab-herstr-01			WINDOW REPAIR	58.80 EUR		58.80 EUR

Interior

[x]	BACK SHELF	CUT / TORN				
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		0 EUR		50 %	

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

HUB CAP FL

			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR				50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK SHELF	50.00 EUR	50 %	50.00 EUR
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
64.58	211.80	58.80	90.00	0	0	0	0	0	0
39.58	105.90	58.80	45.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
73.38	351.80	0	425.18
HOG: 0	BG: 0		NA Deprec. 249.28
			0.00%
			TOTAL 249.28

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 15:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	