

CWNTKT

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	109367 KM
<b>File nr. :</b>	1446238	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EDW350 / WBAFW11030C713712 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	01/11/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	BMW / 5	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	44654	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ARKADIN BENELUX SA	<b>Co2:</b>	125g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	5 BER 520d Start/Stop 163PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>	BERLINE	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	4
<b>HP:</b>	163	<b>kW:</b>	120
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x] OK [x]	1.6-2/	Rim :	[x] WHEEL SCRATCHED	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	X2
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	X2
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	WIND SCREEN/BELOW/RIGHT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
0	560.64	0	0	0	0	0	0	0	0
0	280.32	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	560.64	0	<b>560.64</b>
HOG: 0	BG: 2		NA Deprec. 280.32
			0.00%
			<b>TOTAL 280.32</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 13/10/2017 <b>Hour :</b> 14:43 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	