

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	115106 KM
File nr. :	1447434	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
UQ7972 / VF7KFRHC8DS516639 /		yr of constructionr :	/
E-File nr. :		First registration :	12/11/2013
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / DS5	Fuel type :	HYBRID
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	FERRERO TRADING LUX	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	DS5 Hybrid4 Chic 163PK Aut.	Country registration :	LUXEMBOURG

VAT over the margin - car:	No	Metallic paint:	
Variant car:		Engine size:	1997
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES			CHEMISCHE	
			Repair paint - LI	New paint - E	Depr.	Total
	4	0 LU =0.00 EUR	577.80 EUR		50 %	577.80 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	3	0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
	6	15 LU =72.00 EUR	264.21 EUR		50 %	336.21 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
	7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
	7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
0	254.16	372.60	577.80	63.00	336.21	380.00	0	0	0
0	127.08	186.30	288.90	63.00	168.10	380.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
443.00	1540.77	0	1983.77
HOG: 0	BG: 2		NA Deprec. 1213.38
			0.00%
			TOTAL 1213.38

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOC WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 13:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	