

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	94147 KM
File nr. :	1445869	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FKT703 / VF7UA9HR8DJ684281 /		yr of constructionr :	/
E-File nr. :		First registration :	31/07/2013
VFS-nr. :		Color :	SILVER
Make + Model :	CITROEN / C4 PICASSO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	135g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.C4 PICASSO 7pl.Seduct.FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :		
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x] WHEEL SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	BONNET/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE

Interior

[x]	DASHBORD	SCRATCHED
[x]	DOOR IN REAR RIGHT	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	ROOF/CENTER/RIGHT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 2	i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		195.60 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE		L+R		
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	

1	2	3	4	5	6	7	8	9	10
211.80	211.80	195.60	0	0	0	0	0	0	0
105.90	105.90	195.60	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
195.60	423.60	0	619.20
HOG: 0	BG: 0		NA Deprec. 407.40
			0.00%
			TOTAL 407.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/10/2017 Hour : 15:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	