

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	115184 KM
File nr. :	1448238	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAP769 / WBAXC01090DZ95209 /		yr of constructionr :	/
E-File nr. :		First registration :	04/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	12067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DELOITTE SERVICES & INVESTMENTS NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 GRAN TURISMO 520dA St/St 163PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	245	50	R	18	W
Rear tyre	245	50	R	18	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	362.02 EUR		50 %	362.02 EUR
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR
[x]	REAR WINDOW STYLE/RIGHT/REAR		OTHER DAMAGES	CHEM. INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR
[x]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	REAR DOOR/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	ROOF/REAR/RIGHT		OTHER DAMAGES	HAGEL	
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	ROOF STYLE/CENTER/RIGHT		OTHER DAMAGES	CHEM. INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	264.22 EUR		50 %	264.22 EUR
[x]	REAR DOOR/RIGHT/CENTER		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
9	30 LU =144.00 EUR	0 EUR	522.85 EUR	50 %	666.85 EUR

[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR
[x]	ROOF STYLE/FRONT/LEFT/CENTER	OTHER DAMAGES		CHEM. INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	264.22 EUR		50 %	264.22 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES		CHEM. INWERKING+HAGEL	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Interior

[x]	FLOOR BOOT	DIRTY					
		Number	Code	Description	Unit price	Depr.	Total
10	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR			29.16 EUR

Pieces

		Number	Code	Description	Unit price	Depr.	Total
9	1	DOOR REAR RIGHT		440.64 EUR	50 %		440.64 EUR

1	2	3	4	5	6	7	8	9	10
348.09	254.16	264.22	382.02	369.84	362.02	254.16	634.06	1480.09	29.16
174.04	127.08	132.11	191.01	184.92	181.01	127.08	317.03	740.04	29.16

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	4348.66	0	4377.82
HOG: 0	BG: 2		NA Deprec. 2203.49
			0.00%
			TOTAL 2203.49

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 10:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	