

www.vabfleetservices.be

### **APPRAISAL**

Date : 13/10/2017

### [X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	108638 KM
File nr. :	1445119	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FLX267 / SALFA2DC5DH3	68133 /	yr of constructionr :	2013 / 00
E-File nr. :		First registration :	12/08/2013
VFS-nr. :		Color :	GREEN D
Make + Model :	LAND ROVER / FREELANDER	Fuel type :	DIESEL
Object nr. :	48382	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LBC BELGIUM HOLDING NV	Co2:	165g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FREELANDER 2 Td4 S S/S 150PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	2179
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

1/5

CV7F4W

# fleet services

## **APPRAISAL**

www.vabfleetservices.be

Date :

13/10/2017

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	ОК	[x]	Filled up :	0	

### Wheels and tyres: Summer tires

Real	r tyre			235		65			R	17	V	
Fron	t tyre			235		65			R	17	V	
		[x]		Width			Heigl	ht		Туре	Rim	Index
Wheel RES:	[x]	GOC	DYEAR	Tyre :		OK	[x] >6	6 / <b>Rin</b>	:		/ Hubcap :	
Wheel RR :	[x]	GOC	DYEAR	Tyre :		OK	[x] 2-	-4 / <b>Rin</b>	:		/ Hubcap :	
Vheel FR :	[x]	GOC	DYEAR	Tyre :	[x]	OK	[x] 2-	-4 / <b>Rin</b>	1: [X]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x]	GOC	DYEAR	Tyre :		OK	[x] 2-	-4 / <b>Rin</b>	ı:		/ Hubcap :	
Vheel FL:	[x]	GOC	DYEAR	Tyre :		OK	[x] 2-	-4 / <b>Rin</b>	:		/ Hubcap :	

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/ Hubcap :

[X]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

2/5



### **APPRAISAL**

www.vabfleetservices.be

Date :

13/10/2017

3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

		0!										
RO	dywork v	& window	'S									
[x]	REAR MU	DGUARD/LEFT	CENTER			SCRATCH (WITH	HOUT PAINT D	AMAGE)				
[x]	REAR DO	OR/LEFT/CENT	ER			SCRATCH (WITHOUT PAINT DAMAGE)						
[x]	REAR DO	OR/RIGHT/REA	R			SCRATCH WITH PAINT DAMAGE						
[x]	REAR DO	OR/RIGHT/CEN	TER			SCRATCH (WITH	HOUT PAINT D	AMAGE)				
[x]	FRONT DO	OOR/LEFT/CEN	TER			SCRATCH (WITH	HOUT PAINT D	AMAGE)				
[x]	FRONT DO	OOR/RIGHT/CE	NTER			SCRATCH (WITH	HOUT PAINT D	AMAGE)				
[x]	FRONT BU	UMPER/LEFT				SCRATCH WITH PAINT DAMAGE						
Inte	erior											
[x]	BOOT IN I	R				SCRATCHED						
ст	ATUC.											
51	ATU5:	NOT AC	CEPTAB	LE								
Boo	dywork \	& window	'S									
[x]	FRONT M	UDGUARD/LEF	T/CENTER			SCRATCH WITH PAINT DAMAGE +DEUK						
				Repair pair	nt - LI	New paint - E Depr. Total						
	1 0 LU =0.00	) EUR		220.18 EUF	R					220.18 EUR		
Oth	ers											
	RIM FROM	NT RIGHT										
	Number	Code		Description	1		Unit p	orice Depr		Total		
	<b>1</b> I 1	i-vab-herstalu-02		REPAIR AI	LLOY WHEEL		95.00	EUR		95.00 EUR		
	1	2	3	4	5	6	7	8	9	10		
	315.18	0	0	0	0	0	0	0	0	0		
	315.18	0	0	0	0	0	0	0	0	0		
	INNOV	ATIVE	TRAD	TIONAL	IONAL GENERAL							
	95.	00	22	20.18		0		315.18				
	НОС	<b>3</b> : 0	В	G: 0			NA De	eprec.		315.18		
L							0.00	)%				
							тот	TAL		315.18		



www.vabfleetservices.be

Date : 13/10/2017

4/5

# fleet services

## **APPRAISAL**

www.vabfleetservices.be

Date :

13/10/2017

[x] = Status Modification

#### Pictures : No CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	
NOT EXECUTED :	No				
Reason :					
Remark :					

Prices in EUR without VAT

Authorized by customer :				Executed by VAB Fleet Services
Remark authorized cust	omer :			
Date :	13/10/2017	Hour :	08:54	
Company :				
Executed by VAB Fleet Services				
E-Mail :	@			
Signature authorized by c	ustomer			

5/5