

D2N4XA

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	30202 KM
<b>File nr. :</b>	1450909	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1PNH716 / ZCFC635A605107113 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	11/08/2016
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	IVECO / DAILY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	227g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2998
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	4
<b>HP:</b>	146	<b>kW:</b>	107
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x] BROKEN / CRACKED
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	R
Rear tyre	195	75	R	16	R

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

### Interior

[x]	DASHBOARD	HOLE
-----	-----------	------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT
-----	-----------------------------	------

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Interior

[x]	SEAT FL	BURNT
-----	---------	-------

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-intvnl-01	VINYL REPAIR	82.20 EUR		82.20 EUR

[x]	ROOF UPHOLSTERY	HOLE
-----	-----------------	------

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-intvrl-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED
-----	-------------------------------	------------------

	Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	0 EUR	50 %	48.00 EUR

## Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

## Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	MIRROR	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
63.00	146.52	138.00	22.50	0	0	0	0	0	0
63.00	146.52	69.00	11.25	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
209.52	160.50	0	<b>370.02</b>
HOG: 0	BG: 3		NA Deprec. 289.77
			0.00%
			<b>TOTAL 289.77</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/10/2017 <b>Hour :</b> 10:35 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	