

www.vabfleetservices.be Date: 13/10/2017 1/4

CXRMXN

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 122806 KM File nr. : Mileage start / arrival: 1447090 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EPS570 / WF0GXXGBBGDJ85884 / 2013 / 00 E-File nr. : First registration: 18/02/2013 Color: VFS-nr.: **GREY** Make + Model : Fuel type : FORD / MONDEO CLIPPER **DIESEL** Object nr. : Fuel: 51411 Classification: **Environment Class:** F EURO 5 Customer company: Co2: CEGEKA NV 129g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

MONDEO CLIP Titanium 136PK

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BREAK	Engine size:	1997				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
HP:	136	kW:	100				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:	General condition:						



13/10/2017 www.vabfleetservices.be Date: 2/4

Original registr. number : OK OK Service manual:

Cert. of reg. / Part 1:

Cert. of conformity: OK Insurance certificate: Cert. of reg. copy / Part 2: OK

Warning vest: OK [x] Transport licence:

Tax certificate: Navigation CD/SD/DVD

Fuel card : Car radio: OK

Mobile phone kit : Extinguisher: OK

Warning triangle: OK OK Oil level: OK First aid kit :

Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Summer tires

Wheel FL:		MICHELIN	Tyre:	OK	2-4 /	Rim:		/	Hubcap:
Wheel RL:		GOODYEAR	Tyre:	OK	2-4 /	Rim:		/	Hubcap:
Wheel FR:		MICHELIN	Tyre:	OK	2-4 /	Rim:		/	Hubcap:
Wheel RR:		GOODYEAR	Tyre:	OK	2-4 /	Rim:	WHEEL SCRATCHED	/	Hubcap:
Wheel RES:	[x]	ANDERE	Tyre:	OK	/	Rim : [x]		/	Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/10/2017 3/4

Conclusion

Bodywork \& windows

[x] REAR WINDOW/LEFT

STICKER(S)

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT DENT

[x] REAR DOOR/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/FRONT DENT

[x] REAR DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE RAND

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE RAND

[x] BONNET/CENTER/LEFT CHIPS

Interior

SEAT FL

SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 13/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No						
Remark :	NAVI OK [x]						
Prices in EUR w	ithout VAT						
Authorized by customer:			Executed by VAB Float	eet Services			
Remark authorized o	customer :						
Date : Company :	13/10/2017	Hour: 09:17					
Executed by VAB Flo Services	eet						
E-Mail :	@						
Signature authorized b	by customer						