

CUXOYR

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	22470 KM
<b>File nr. :</b>	1444905	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EOU926 / JTHKD5BH202120396 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	11/02/2013
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	LEXUS / CT	<b>Fuel type :</b>	ELECTRICITY
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INT. CARRIER SERVICES NV	<b>Co2:</b>	94g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	ALCANTARA	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	CT 200h BER Comfort Line E-CVT 99PK Aut.	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1798
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	99	<b>kW:</b>	73
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] >6/ Rim : [x] MISSING/INCOMPLETE / Hubcap :
Wheel RL : [x] GOODYEAR Tyre : OK [x] >6/ Rim : / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] GOODYEAR Tyre : OK [x] >6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	WINTER H
Rear tyre	205	60	R	16	WINTER H

Remark : REPSET OK

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
1	10 LU =48.00 EUR	211.80 EUR		50 %	259.80 EUR	
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
2	5 LU =24.00 EUR	308.20 EUR		50 %	332.20 EUR	
[x]	REAR DOOR/LEFT/CENTER		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	ROOF STYLE/CENTER/LEFT		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	ROOF STYLE/CENTER/RIGHT		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	FRONT THRESHOLD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR	
[x]	BONNET/CENTER/RIGHT		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	FRONT MUDGUARD/RIGHT/FRONT		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	ROOF/CENTER/LEFT		DENT		HAGEL/BESTEK VIA INFORMEX	
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					

## Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

## Others

RIM FRONT LEFT

		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR			50 %	

## Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	MIRROR	120.00 EUR	50 %	120.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	EMBLEM	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
259.80	332.20	310.50	168.00	20.00	0	0	0	0	0
129.90	166.10	155.25	84.00	10.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1090.50	0	<b>1090.50</b>
HOG: 0	BG: 0		NA Deprec. 545.25
			0.00%
			<b>TOTAL 545.25</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> VRTG MET HAGELSCHADE/BESTEK VIA INFORMEX [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b> 2DE SLEUTEL THUIS  <b>Date :</b> 12/10/2017 <b>Hour :</b> 14:26  <b>Company :</b>  <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	