

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	115947 KM
File nr. :	1446934	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CIN888 / WF0SXXGBWSBM17795 /		yr of constructionr :	/
E-File nr. :		First registration :	06/12/2011
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / S-MAX	Fuel type :	DIESEL
Object nr. :	59779	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	R.I.C.	Co2:	149g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	5 [x]
Vehicle type :	S-MAX Titanium DPF 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	FRONT MUDGUARD/LEFT/CENTER		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR		0 EUR	237.22 EUR	50 %	357.22 EUR

Interior

[x]	BOOT LID IN		CARVED			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
2	1	FENDER FL		172.80 EUR	50 %	172.80 EUR

1	2	3	4	5	6	7	8	9	10
110.64	530.02	110.64	0	0	0	0	0	0	0
110.64	265.01	110.64	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
221.28	530.02	0	751.30
HOG: 0	BG: 0		NA Deprec. 486.29
			0.00%
			TOTAL 486.29

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	