

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	157194 KM
File nr. :	1447237	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
PH8872 / WF0SXXBDFSBJ19314 /		yr of constructionr :	/
E-File nr. :		First registration :	20/10/2011
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	SOLUDEC	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	9 [x]
Vehicle type :	TRANSIT 300S MBUS SWB Ambiente 115PK	Country registration :	LUXEMBOURG

VAT over the margin - car:	No	Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	2198
Gear box :	Manueel	Number of places:	9
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD		
Mobile phone kit :		Car radio :		
First aid kit :	OK	[x]		
Jack, wheelspanner :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	70	R	15	T
Rear tyre	195	70	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	X5
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	DENT	
[x]	REAR DOOR/LEFT/LEFT	DENT	X5

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
6	0 LU	=0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]	ROOF/CENTER/RIGHT	DENT			HAGELSCHADE	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/RIGHT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
8	20 LU	=96.00 EUR	238.76 EUR		50 %	334.76 EUR
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			ROEST	
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU	=0.00 EUR	238.76 EUR		50 %	238.76 EUR

[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT BUMPER/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.	Total
9	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
3	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR
9	1	MIRROR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
0	398.40	395.40	110.64	238.76	238.76	63.00	334.76	114.00	0
0	199.20	197.70	110.64	119.38	119.38	63.00	167.38	57.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.64	1720.08	0	1893.72
HOG: 0	BG: 3		NA Deprec. 1033.68
			0.00%
			TOTAL 1033.68

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOC WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 12:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	