

D2M1R5

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: VERY DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	65026 KM
<b>File nr. :</b>	1450887	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GSJ247 / ZCFC50A400D494509 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	15/04/2014
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	IVECO / DAILY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	244g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	No
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2998
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	146	<b>kW:</b>	107
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	/		Rim :	/	Hubcap :
									[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	R
Rear tyre	195	75	R	16	R

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	

### Interior

[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

### Accessories and others

[x]	OUTSIDE MIRROR	SCRATCH WITH PAINT DAMAGE
[x]	VEH COVERED WITH STICKERS	STICKER(S)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR LIGHT/LEFT	DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR DOOR/CENTER/RIGHT	DENT			
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/LEFT/CENTER	DENT			MEERDERE/VOLLEDIGE FLANK
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 5 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		99.00 EUR

[x]	ROOF/CENTER/RIGHT		DENT		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	80 LU =384.00 EUR	0 EUR	639.63 EUR	50 %	1023.63 EUR

[x]	REAR DOOR/RIGHT/FRONT		DENT		
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	BONNET/CENTER/RIGHT/FRONT		DENT		ONGEVALSSCHADE
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	35 LU =168.00 EUR	0 EUR	307.10 EUR	50 %	475.10 EUR

[x]	FRONT/LEFT		OTHER DAMAGES		VOORBEHOUD ACHTERLIGGENDSCHADE
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0				

[x]	FRONT/RIGHT		HOLE/CRACK/TORN		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	10 LU =48.00 EUR	0 EUR	186.28 EUR	50 %	234.28 EUR

## Interior

[x]	BOOT LID IN		OTHER DAMAGES		
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 9 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		168.66 EUR

## Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 10	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	114.70 EUR
1	I 10	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	114.70 EUR
1	I 6	bestelwagen-laadruimte-a-vab-rein-06	CLEANING INTERIOR	22.94 EUR	137.64 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	BONNET	401.40 EUR	50 %	401.40 EUR
2	1	GRILL	75.00 EUR	50 %	75.00 EUR
4	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR
7	1	ROOF	450.00 EUR	50 %	450.00 EUR

1	2	3	4	5	6	7	8	9	10
535.70	1185.78	162.00	91.50	63.00	63.00	1473.63	0	0	0
535.70	592.89	162.00	45.75	63.00	63.00	736.82	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
823.70	2750.91	0	<b>3574.61</b>
HOG: 0	BG: 3		NA Deprec. 2199.16
			0.00%
			<b>TOTAL 2199.16</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/10/2017 <b>Hour :</b> 14:51 <b>Company :</b> <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	