

www.vabfleetservices.be Date: 17/10/2017 1/4

CZDAN3

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 194480 KM File nr. : Mileage start / arrival: 0 / 01448306 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DRF417 / WF0LXXGCBLCK46520 / E-File nr. : First registration: 31/07/2012 Color: VFS-nr.: WHITE Make + Model : Fuel type : FORD / FOCUS CLIPPER **DIESEL** Object nr. : Fuel: 8676 Classification: **Environment Class:** EURO 5 Customer company: Co2: G4S SECURITY SYSTEMS NV 109g/km Driver : Remote controls: TISSUE Covering: Number keys: 2[x]Vehicle kind: Seats (minivan): 0

Country registration:

BELGIUM

FOCUS CLIP. ECOnetic T.Trend 95PK

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 17/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	[x]	SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	[x]	SCRATCHED
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	[x]	SCRATCHED
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	[x]	SCRATCHED
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:		
			**** 1.1				• • •		T	ì	D:	_	

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
1					

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] ROOF STYLE/CENTER/LEFT DENT

[x] ROOF/FRONT/CENTER/RIGHT DENT

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] ROOF/CENTER/LEFT DENT

Accessories and others

[x] VEH COVERED WITH STICKERS

STICKER(S)

	1	2	3	4	5	6	7	8	9	10
ĺ	0	0	0	0	0	0	0	0	0	0
ſ	0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0

0.00% TOTAL



17/10/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

TANCES		NORMAL CONCLUSION					
0 min	Waiting time: 0 m Reason:	nin	Towing time : Reason :	0 min			
No	I		1				
ithout VAT							
		Executed by VAB Fleet S	ervices				
customer :							
17/10/2017	Hour: 14:19						
eet							
@							
y customer							
	0 min No ithout VAT ustomer: 17/10/2017	0 min Waiting time : 0 r Reason :	Waiting time: 0 min Reason: No Executed by VAB Fleet S 17/10/2017 Hour: 14:19 Set @	O min Waiting time : O min Reason : Reason : No			