

D2NHNU

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	30522 KM
File nr. :	1450915	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PPY241 / ZCFC635AX05107115 /		yr of constructionr :	/
E-File nr. :		First registration :	25/08/2016
VFS-nr. :		Color :	WHITE
Make + Model :	IVECO / DAILY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	227g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	2998
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	146	kW:	107
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres:

Wheel FL:	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK /	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK /	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK /	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] REAR DOOR/CENTER/LEFT DENT LAKSCHADE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	226.26 EUR		50 %	226.26 EUR

[x] REAR BUMPER/SIDE/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] REAR DOOR/RIGHT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT BUMPER/LEFT/CORNER HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
2 20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Interior

[x] BOOT IN L CUT / TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 8	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	116.64 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
1	1	BEKLEDING	20.00 EUR	50 %	20.00 EUR
6	1	PINKER	20.00 EUR	50 %	20.00 EUR
6	1	MIRROR GLASS	13.50 EUR	50 %	13.50 EUR

1	2	3	4	5	6	7	8	9	10
136.64	398.40	110.64	226.26	110.64	57.50	63.00	0	0	0
126.64	199.20	110.64	113.13	110.64	28.75	63.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
400.92	702.16	0	1103.08
HOG: 0	BG: 3		NA Deprec. 752.00
			0.00%
			TOTAL 752.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 15:06 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	