

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	122727 KM
File nr. :	1448904	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FT0010 / WF0LXXGCBLDC82025 /		yr of constructionr :	/
E-File nr. :		First registration :	21/10/2013
VFS-nr. :		Color :	BROWN
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :	70798	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	HAASAUTOMATIONEUROPE	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. EConetic Titanium 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR

Interior

[x]	SEAT FL		HOLE			
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR	50 %	64.32 EUR
[x]	BOOT LID IN		SCRATCHED			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED			
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
5	1	MIRROR COVER		120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	318.35	64.32	110.64	144.00	0	0	0	0	0
63.00	159.18	32.16	110.64	72.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
237.96	462.35	0	700.31
HOG: 0	BG: 0		NA Deprec. 436.98
			0.00%
			TOTAL 436.98

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 10:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	