

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	81296 KM
File nr. :	1446147	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KXN135 / WDD1760121V076901 /		yr of constructionr :	/
E-File nr. :		First registration :	24/07/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	45730	Fuel :	
Classification :	N	Environment Class:	EURO 6
Customer company :	KPMG TAX AND LEGAL ADVISERS	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	0-1.6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	0-1.6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 10 LU =48.00 EUR	211.80 EUR		50 %	259.80 EUR

[x] REAR DOOR/LEFT/Front SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] REAR DOOR/RIGHT/CORNER/BELOW DENT

Number	Code	Description	Unit price	Depr.	Total
1	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
115.56	211.80	318.35	259.80	0	0	0	0	0	0
115.56	105.90	159.18	129.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	789.95	0	905.51
HOG: 0	BG: 0		NA Deprec. 510.54
			0.00%
			TOTAL 510.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 11:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	