

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	30862 KM
File nr. :	1450902	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PYU161 / ZCFC635A705113647 /		yr of constructionr :	/
E-File nr. :		First registration :	13/10/2016
VFS-nr. :		Color :	WHITE
Make + Model :	IVECO / DAILY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	227g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2998
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	146	kW:	107
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	R
Rear tyre	195	75	R	16	R

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT						
			Repair paint - LI	New paint - E	Depr.	Total		
1	25 LU =120.00 EUR	0 EUR			50 %	120.00 EUR		
[x]	REAR DOOR/CENTER/RIGHT	DENT						
			Repair paint - LI	New paint - E	Depr.	Total		
2	0 LU =0.00 EUR	226.26 EUR			50 %	226.26 EUR		
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE						
			Number	Code	Description	Unit price	Depr.	Total
3	1	i-vab-herstr-01			WINDOW REPAIR	58.80 EUR		58.80 EUR

Accessories and others

[x]	SIDE PROTECTION	BROKEN / CRACKED				
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

1	2	3	4	5	6	7	8	9	10
377.40	226.26	58.80	10.80	0	0	0	0	0	0
188.70	113.13	58.80	5.40	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.80	614.46	0	673.26
HOG: 0	BG: 3		NA Deprec. 366.03
			0.00%
			TOTAL 366.03

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 10:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	