

CX404X

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	83938 KM
File nr. :	1446570	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KPX729 / WDD1760121V068538 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	3735	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	KPMG BEDRIJFSREVISOREN CVBA	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
60.00	63.00	0	0	0	0	0	0	0	0
30.00	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	60.00	0	123.00
HOG: 0	BG: 0		NA Deprec. 93.00
			0.00%
			TOTAL 93.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 13:19 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	