

CX26CX

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	42230 KM
File nr. :	1446532	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HJV544 / WDD1760121V024608 /		yr of constructionr :	/
E-File nr. :		First registration :	05/08/2014
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	70432	Fuel :	
Classification :	N	Environment Class:	EURO 5
Customer company :	Kratos Law CVBA	Co2:	92g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	DENT
[x]	FRONT DOOR/LEFT/FRONT	DENT
[x]	FRONT DOOR/RIGHT/FRONT	DENT
[x]	BONNET/CENTER/RIGHT	DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR THRESHOLD/LEFT/REAR			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	REAR DOOR/RIGHT/FRONT			DENT		
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Interior

[x]	LUGGAGE COVER	MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	

### Others

HUB CAP REAR RIGHT				
	Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		50 %	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
355.56	63.00	30.00	0	0	0	0	0	0	0
235.56	63.00	15.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	270.00	0	448.56
HOG: 0	BG: 0		NA Deprec. 313.56
			0.00%
			TOTAL 313.56

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 13/10/2017      Hour : 11:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	