

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	80957 KM
<b>File nr. :</b>	1448066	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DWY159 / W0LPC6DA8DG010816 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	21/09/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	OPEL / ASTRA	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	11035	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	LANDELIJKE THUISZORG VZW	<b>Co2:</b>	104g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	ASTRA BER ecoFLEX Essentia S&S 95PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1248
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	95	<b>kW:</b>	70
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES	INWERKING	
		Repair paint - LI	Depr.	Total
	1 0 LU =0.00 EUR	481.50 EUR	50 %	481.50 EUR

1	2	3	4	5	6	7	8	9	10
481.50	0	0	0	0	0	0	0	0	0
240.75	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	481.50	0	481.50
HOG: 0	BG: 0		NA Deprec. 240.75
			0.00%
			TOTAL 240.75

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/10/2017 <b>Hour :</b> 08:34 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	