

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	84473 KM
File nr. :	1450396	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FVA251 / W0LPD8EW6E8015124 /		yr of constructionr :	/
E-File nr. :		First registration :	04/11/2013
VFS-nr. :		Color :	GREY
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Vamix nv	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFLEX Business 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :		
First aid kit :		Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	[x]	NOK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	V
Rear tyre	215	60	R	16	V

Remark : PNEUS HIVER AV GAUCHE!!!!!!!!!!!!!!!

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
3	15 LU =72.00 EUR		0 EUR	235.80 EUR	50 %
					307.80 EUR
[x]	REAR LIGHT/RIGHT	HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.
					Total
3	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	30 LU =144.00 EUR		301.68 EUR		50 %
					445.68 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	20 LU =96.00 EUR		308.20 EUR		50 %
					404.20 EUR
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR

Interior

[x] FLOOR BOOT STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

TYRE SPARE WHEEL

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR				

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1 REAR BUMPER		343.20 EUR	50 %	343.20 EUR

Number	Code	Description	Unit price	Depr.	Total
3	1 REAR LIGHT		90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1 REPAIR KIT TYRES		210.53 EUR		210.53 EUR

1	2	3	4	5	6	7	8	9	10
14.58	211.80	1614.88	210.53	0	0	0	0	0	0
14.58	105.90	807.44	210.53	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	2037.21	0	2051.79
HOG: 0	BG: 0		NA Deprec. 1138.45
			0.00%
			TOTAL 1138.45

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 13:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	